

6.1. LAB EQUIPMENT SAFING AND RETRIEVAL

(EMER/5A - ALL/FIN B/MULTI)Page 1 of 1 page

NOTE

1. Relocate all equipment to Node 1 (minimum), SM (desirable).
2. Perform if time available.

EQUIPMENT RETRIEVAL

1. Disconnect CD Library, File Server, and MACE (Mass Access Computer Equipment) from the UOP and relocate. These items share a W power cord.

PEP
Locker

2. Remove all PBAs and PFEs from Locker and relocate.

FGB
427/426

3. Remove AMP, ALSP, and Defib and relocate.